## Fiber inspection probe EXFO FIP-400

With EXFO's FIP-400 Fiber Inspection Probeit is possible to check connectors and other fiber terminations for polish quality and cleanliness. Benefit from the best optical resolution in the industry and see scratches and dirt particles as small as 1  $\mu$ m. Also, use a USB converter to send image captures to a portable platform or a PC. Field of view of this equipment is 412  $\mu$ m x 306  $\mu$ m.



http://www.exfo.com/Documents/TechDocuments/Specification\_Sheets/FIP-400.9-angHR.pdf